



Fatigue according to F.E.M. 1.001  
and compare with Eurocode 3

3.1.2017  
version 4.0

# Content

This step-by-step tutorial demonstrates how to implement the fatigue check according F.E.M. I.001 in SDC Verifier.

The following steps are covered:

- ▶ FEM I.001 Fatigue detailed review;
- ▶ Implementation in SDC Verifier;
- ▶ Weld Finder Tool overview;
- ▶ Fatigue tables and plots;
- ▶ Report preparation and results.

# Fatigue F.E.M. 1.001

## Allowable Stress Design method

The following formulae give for all values of  $\kappa$  the permissible stresses for fatigue

a)  $\kappa \leq 0$

- for tension :  $\sigma_t = 5 \cdot \sigma_w / (3 - 2 \cdot \kappa)$  (1)

- for compression :  $\sigma_c = 2 \cdot \sigma_w / (1 - \kappa)$  (2)

$\sigma_w$  is given in table above.

b)  $\kappa > 0$

- for tension  $\sigma_t = \sigma_0 / [1 - \kappa \cdot (1 - \sigma_0 / \sigma_{+1})]$  (3)

- for compression  $\sigma_c = 1,2 \cdot \sigma_t$  (4)

where  $\sigma_0$  = tensile stress for  $\kappa = 0$  is given by the formula (1) that is :

$$\sigma_0 = 1,66 \cdot \sigma_w$$

$\sigma_{+1}$  = tensile stress for  $\kappa = +1$  that is the ultimate strength  $\sigma_R$  divided by the coefficient of safety

$$4/3 : \sigma_{+1} = 0,75 \cdot \sigma_R$$

$\sigma_t$  is limited in every case to  $0,75 \cdot \sigma_R$ .

By way of illustration, fig. A.3.6.1. shows curves giving the permissible stress as a function of the ratio  $\kappa$  for the following cases :

- steel A.52 ;
- predominant tensile stress ;
- group E6 ;
- construction cases  $W_0, W_1, W_2$  for unwelded components and cases of construction for joints  $K_0$  to  $K_4$ .

The permissible stresses have been limited to  $240 \text{ N/mm}^2$ , i.e. to the permissible stress adopted for checking for ultimate strength.




Figure A.3.6.1. - (A 52; tension; group E6)

# Fatigue in SDC Verifier

## Kappa Factor

$$\kappa_x = \sigma_{x \min} / \sigma_{x \max}$$

$$\kappa_y = \sigma_{y \min} / \sigma_{y \max}$$

$$\kappa_{xy} = \tau_{xy \min} / \tau_{xy \max}$$

## Allowable Stress

a)  $\kappa \leq 0$

- for tension :

$$\sigma_t = 5 \cdot \sigma_w / (3 - 2 \cdot \kappa) \quad (1)$$

- for compression :

$$\sigma_c = 2 \cdot \sigma_w / (1 - \kappa) \quad (2)$$

$\sigma_w$  is given in table above.

b)  $\kappa > 0$

- for tension

$$\sigma_t = \sigma_0 / [1 - \kappa \cdot (1 - \sigma_0 / \sigma_{t \max})] \quad (3)$$

- for compression

$$\sigma_c = 1.2 \cdot \sigma_t \quad (4)$$

## Utilization Factor Combined

$$(\sigma_{x \max} / \sigma_{x \alpha})^2 + (\sigma_{y \max} / \sigma_{y \alpha})^2 - \\ \sigma_{x \max} \cdot \sigma_{y \max} / (|\sigma_{x \alpha}| \cdot |\sigma_{y \alpha}|) + \\ (\tau_{xy \max} / \tau_{xy \alpha})^2 \leq 1$$

where the stress values  $\sigma_{x \alpha}$ ,  $\sigma_{y \alpha}$  and  $\tau_{xy \alpha}$  are those resulting from the application of formulae (1), (2), (3) and (4) limited to  $0.75 \cdot \sigma_R$ .

Add Custom Check

ID	2	Title	Fatigue Check
Alias	Fatigue_Check	Description	
<input checked="" type="checkbox"/> Show Parameter Description			

Options

Calculate Results over Directions

Calculate Results over Points

Load Calculation

Selection All Entities

Parameters (4) / Replacements (0)

Parameter = Kappa (Kappa Factor)  
All: if(SweldAbs > 0, SweldMin / SweldMax, SweldMax / SweldMin)

Parameter = Sf (Stress Fatigue)  
All: Min(units.FromPaToCurrent(Switch(MaterialType, Fe360, Sf\_Fe360(ElementGroup, WeldType), Fe510, Sf\_Fe510(ElementGroup, WeldType))), Static\_Check.Sallow)

Parameter = Sallow\_fatigue (Allowable Stress Fatigue)  
All: if (Kappa > 0, if(SweldAbs > 0, (5 / 3 \* Sf) / (1 - (1 - (5 / 3 \* Sf) / (0.75 \* tensile)) \* Kappa), (2 \* Sf) / (1 - (1 - (2 \* Sf) / (0.9 \* tensile)) \* Kappa)), if(SweldAbs > 0, (5 \* Sf) / (3 - 2 \* Kappa), (2 \* Sf) / (1 - Kappa)))  
Eqv.: 0

Parameter = Uf (Utilization Factor)  
All: Abs(SweldAbs) / Min(Static\_Check.Sallow, Sallow\_Fatigue)  
XY: Abs(SweldAbs) / (Min(Static\_Check.Sallow, Sallow\_Fatigue / if(WeldType <= Weld\_K4, SQRT(2), SQRT(3))))  
YZ: Abs(SweldAbs) / (Min(Static\_Check.Sallow, Sallow\_Fatigue / if(WeldType <= Weld\_K4, SQRT(2), SQRT(3))))  
ZX: Abs(SweldAbs) / (Min(Static\_Check.Sallow, Sallow\_Fatigue / if(WeldType <= Weld\_K4, SQRT(2), SQRT(3))))  
Eqv.: pow(me.x, 2) + pow(me.y, 2) + pow(me.z, 2) + pow(me.xy, 2) + pow(me.yz, 2) + pow(me.zx, 2) - sign(SweldAbs.X) \* me.x \* sign(SweldAbs.Y) \* me.y - sign(SweldAbs.Y) \* me.y \* sign(SweldAbs.Z) \* me.z - sign(SweldAbs.Z) \* me.z \* sign(SweldAbs.X) \* me.x  
Overall: Max(me.x, me.y, me.z, me.xy, me.yz, me.zx, sqrt(me.eqv / 1.1))

OK Cancel Clear results

# Stress Fatigue

Stress Fatigue is used in Fatigue Allowable Stress calculations.

$$\kappa \leq 0$$

- for tension :  $\sigma_t = 5 \cdot \sigma_w / (3 - 2 \cdot \kappa) \quad (1)$

- for compression :  $\sigma_c = 2 \cdot \sigma_w / (1 - \kappa) \quad (2)$

Stress Fatigue depends on:

- Weld Type (W0-W2, K0-K4);
- Element Group / Loading Group (B1-B6);
- Material Type (St360/St37, St510/St52).

Table T.A.3.6.1.  
Values of  $\sigma_w$  depending on the component group and construction case (N/mm<sup>2</sup>)

Com- ponent group	Unwelded components Construction cases						Welded components Construction cases (Steels St 37 to St 52, Fe 360 to Fe 510)				
	W <sub>0</sub>		W <sub>1</sub>		W <sub>2</sub>		K <sub>0</sub>	K <sub>1</sub>	K <sub>2</sub>	K <sub>3</sub>	K <sub>4</sub>
	Fe 360 St 37 St 44	Fe 510 St 52 St 44	Fe 360 St 37 St 44	Fe 510 St 52 St 44	Fe 360 St 37 St 44	Fe 510 St 52 Fe 510					
E1	249,1	298,0	211,7	253,3	174,4	208,6	(361,9)	(323,1)	(271,4)	193,9	116,3
E2	224,4	261,7	190,7	222,4	157,1	183,2	(293,8)	262,3	220,3	157,4	94,4
E3	202,2	229,8	171,8	195,3	141,5	160,8	238,4	212,9	178,8	127,7	76,6
E4	182,1	201,8	154,8	171,5	127,5	141,2	193,5	172,8	145,1	103,7	62,2
E5	164,1	177,2	139,5	150,6	114,9	124,0	157,1	140,3	117,8	84,2	50,5
E6	147,8	155,6	125,7	132,3	103,5	108,9	127,5	113,8	95,6	68,3	41,0
E7	133,2	136,6	113,2	116,2	93,2	95,7	103,5	92,4	77,6	55,4	33,3
E8	120,0	120,0	102,0	102,0	84,0	84,0	84,0	75,0	63,0	45,0	27,0

Corresponding values of Stress fatigue in SDC Verifier:

Extreme	X	Y	Z	XY	YZ	ZX	Eqv.	Overall
Minimum	95.60e+6	113.80e+6	127.50e+6				147.80e+6	0.00e+0
Value	95.60e+6	113.80e+6	127.50e+6				147.80e+6	0.00e+0
Maximum								
Element ID	1	326		326			1	1
Load Group	1..Load Group 1							
Table Type	Parameter over Directions							
Parameter	Stress Fatigue							

# Weld Type


Weld Type – also called Notch Case, defines which elements belong to what weld type (K0-K4 – joints affected by welding, W0-W2 – elements and joints, not affected by welding). Weld Type depends on shape, structural design, whole pattern or type and quality of welds.

Case W <sub>0</sub>			
Reference	Description	Figure	Symbol
W <sub>0</sub>	Parent metal, homogeneous surface. Part without joints or breaks in continuity (solid bars) and without notch effects unless the latter can be calculated.		



Case K<sub>0</sub> - Slight stress concentration

Reference	Description	Figure	Symbol
0,1	Parts butt-welded (S.Q.) at right angles to direction of forces		P 100 


Case K<sub>1</sub> - Moderate stress concentration

Reference	Description	Figure	Symbol
1,1	Parts joined by butt welding (O.Q.) at right angles to the direction of the forces		



Case K<sub>2</sub> - Medium stress concentration

Reference	Description	Figure	Symbol
2,1	Parts of different thickness butt welded (O.Q.) at right angles to the direction of the forces. Asymmetrical slope : 1 in 3 (or symmetrical slopes : 1 in 2)		
2,4	Cruciform joint made with K-welds (S.Q.) perpendicular to the direction of the forces		D 

Case K<sub>3</sub> - Severe stress concentration

Reference	Description	Figure	Symbol
3,11	Butt weld with backing strip and no backing run. Backing strip secured by intermittent tack welds		<
3,4	Cruciform joint made with K-weld (O.Q.) at right angles to the direction of the forces		D 

Case K<sub>4</sub> - Very severe stress concentration

Reference	Description	Figure	Symbol
4,1	Parts of different thickness butt welded (O.Q.) at right angles to the direction of the forces. Asymmetrical position without blend slope		
4,4	Cruciform joint made with fillet weld (O.Q.) at right angles to the direction of the forces		D 

# Element Group

Element Group also called Loading Group depends on: Class of Utilization, Load Spectrum.

Example of Load Cycles:

Load Cycles	Number	Total
Moves per hour	30	
Hours per day	10	300
Days per year	300	90000
Number of Years	20	1800000
Total	Million:	1.8

Class of Utilization **B7** (1.8 million <  $2 \times 10^6$ )

Table T.2.1.4.2. - Classes of utilization

Symbol	Total duration of use (number n of stress cycles)		
B0		n	$\leq$
B1	16 000	<	n
B2	32 000	<	n
B3	63 000	<	n
B4	125 000	<	n
B5	250 000	<	n
B6	500 000	<	n
<b>B7</b>	1 000 000	<	n
B8	2 000 000	<	n
B9	4 000 000	<	n
B10	8 000 000	<	n

Table T.2.1.4.3. - Spectrum classes

Symbol	Spectrum factor	$k_{sp}$	$\leq$	0,125
P1				
P2	0,125	<	$k_{sp}$	$\leq$ 0,250
P3	0,250	<	$k_{sp}$	$\leq$ 0,500
P4	0,500	<	$k_{sp}$	$\leq$ 1,000

$$k_{sp} = (\sigma_1 / \sigma_{max})^c (n_1 / n) + (\sigma_2 / \sigma_{max})^c (n_2 / n) + \dots + (\sigma_r / \sigma_{max})^c (n_r / n) = \sum_{i=1}^r [(\sigma_i / \sigma_{max})^c (n_i / n)]$$

$$n_1 + n_2 + \dots + n_r = \sum_{i=1}^r n_i = n$$

Element Group

Table T.2.1.4.4. - Component groups

Stress Spectrum class	Class of utilization										
	B0	B1	B2	B3	B4	B5	B6	<b>B7</b>	B8	B9	B10
P1	E1	E1	E1	E1	E2	E3	E4	E5	E6	E7	E8
<b>P2</b>	E1	E1	E1	E2	E3	E4	E5	<b>E6</b>	E7	E8	E8
P3	E1	E1	E2	E3	E4	E5	E6	E7	E8	E8	E8
P4	E1	E2	E2	E4	E5	E6	E7	E8	E8	E8	E8


# Open the starter model

1

Launch SDC Verifier 

2


Open project *F.E.M. 1.001* from the directory *Tutorials/F.E.M. 1.001*.



# Run Analysis

1

Press ▶ to start Analysis in Femap



# Weld Finder

1

Execute Recognition =>Weld Finder =>  
Edit...

2

Press Find Welds.

3

Press Export


Selection - Part of the model where to find welds

Move Welds. Order is important when one element belongs to 2 welds.

Add, Edit, Combine and Remove Welds.

Preview and Export selected welds

Plot of selected welds in colors and with labels of IDs



The screenshot shows the 'Welds Finder' dialog box. In the 'Settings' section, the 'Selection' dropdown is set to 'All Entities' (highlighted with a red box). Other settings include 'Default Title', 'Check on Free Edges before search', 'Treat as weld if different properties', and 'Treat Allowable angle between elements in one weld' (set to 3°). Below these are two preview images: one showing a 3D model with two welds labeled 'Weld 1' and 'Weld 2' at an angle, and another showing a 3D model with a weld labeled 'A'. The 'Welds' section contains a table with 31 rows, each listing an ID, title, element count, and node count. At the bottom of the dialog are three buttons: 'Find Welds' (highlighted with a red box), 'Export' (highlighted with a red box), and 'OK/Cancel' buttons.

ID	Title	Elements Count	Nodes Count
1	1 (X = -30.11; Y = 12.75; Z = 4.07)	201	68
2	2 (X = -29.94; Y = 12.75; Z = 8.36)	486	163
3	3 (X = -29.94; Y = 12; Z = 8.41)	504	169
4	4 (X = -29.6; Y = 12.6; Z = 8.37)	522	175
5	5 (X = -29.6; Y = 12.38; Z = 6.48)	210	71
6	6 (X = -29.6; Y = 12.38; Z = 7.79)	3	2
7	7 (X = -29.6; Y = 12.38; Z = 7.81)	3	2
8	8 (X = -29.6; Y = 12.38; Z = 9.69)	306	103
9	9 (X = -29.6; Y = 12.12; Z = 10.09)	240	81
10	10 (X = -30.27; Y = 12.75; Z = 8.36)	486	163
11	11 (X = -30.27; Y = 12; Z = 8.41)	504	169
12	12 (X = -30.61; Y = 12.6; Z = 8.37)	522	175
13	13 (X = -30.61; Y = 12.38; Z = 6.48)	210	71
14	14 (X = -30.61; Y = 12.38; Z = 7.79)	3	2
15	15 (X = -30.61; Y = 12.38; Z = 7.81)	3	2
16	16 (X = -30.61; Y = 12.38; Z = 9.69)	306	103
17	17 (X = -30.61; Y = 12.12; Z = 10.09)	240	81
18	18 (X = -29.61; Y = 12.51; Z = 2.61)	22	12
19	19 (X = -29.61; Y = 12.47; Z = 2.87)	27	10
20	20 (X = -29.61; Y = 12.47; Z = 4.17)	27	10
21	21 (X = -29.61; Y = 12.51; Z = 5.47)	20	14

# Weld Finder. Export

4



**All welds as one component ON**  
**All welds as one group ON**

Femap group and new component will be created.

5


Press OK.

It is possible to export weld intersections into component (Nodal or Elemental)



# Stress Transformation

Stresses for weld elements are automatically transformed in the direction of the corresponding weld from Weld Finder Tool using the wedge method. Stresses are transformed only for plate type elements.



$$\sigma_{nn} = \frac{(\sigma_{xx} + \sigma_{yy})}{2} + \frac{(\sigma_{xx} - \sigma_{yy})}{2} * \cos 2\theta + \tau_{xy} * \sin 2\theta$$

$$\tau_{nt} = -\frac{(\sigma_{xx} - \sigma_{yy})}{2} * \sin 2\theta + \tau_{xy} * \cos 2\theta$$

$$\sigma_{tt} = \frac{(\sigma_{xx} + \sigma_{yy})}{2} - \frac{(\sigma_{xx} - \sigma_{yy})}{2} * \cos 2\theta - \tau_{xy} * \sin 2\theta$$

$\sigma_{xx}, \sigma_{yy}, \tau_{xy}$  – original x, y and shear stress in local element x, y and shear directions


$\sigma_{tt}, \sigma_{nn}, \tau_{nt}$  – transformed x, y and shear stress in weld x, y and shear directions

$\theta$  – angle between the element and weld x directions.

# Add Standard

1

Execute **Add => F.E.M. 1.001** in Standards context menu.



**F.E.M. 1.001** - performs static stress check and fatigue check for steel structures of crane and crane equipment. Fatigue calculations are performed according to Allowable Stress Design method (ASD).

# F.E.M. 1.001 Standard

1

Selection: All Entities

2

Press  to edit material properties.

Amount of materials with not defined Tensile or Yield are displayed in the field

3



Tensile Strength: **360e6**

Yield Stress: **240e6** and Press Set.

4

Press OK.

*Unit System.* Stress Fatigue values are constant for specified material and are measured in Pa. Changing unit system enables to convert Pa into Mpa, for example.



# Definition of weld categories

- ▶ Weld/notch category determines fatigue resistance
- ▶ Division in welds / non welds for FEM I.001:
  - ▶ W category is for non welded parts
  - ▶ K category is for welded parts
- ▶ Fatigue resistance is further specified by adding classes
  - ▶ W0-W2 for non-welded parts
  - ▶ K0-K4 for welded parts
- ▶ Better fatigue resistance results in lower class number

# Weld Classes depends on Weld Type

## Non-weld group W0

nr.	description of the main types	symbol
W01	Part without hole and without joint, with a normal state of the surface, without notch behaviour.	

## Slight notch behavior group K0

nr.	description of the main types	symbol
011	Parts, jointed by a butt weld of special quality, perpendicular to the direction of force.	

## Moderate notch behavior group K1

nr.	description of the main types	symbol
111	Parts, jointed by a butt weld of ordinary quality, perpendicular to the direction of force.	

## Medium notch behavior group K2

nr.	description of the main types	symbol
211	Profiles, jointed by butt welds of special quality, perpendicular to the direction of force.	

## Great notch behavior group K3

311	Parts jointed by a <u>butt weld</u> with a <u>backing strap</u> , without sealing run and perpendicular to the direction of force. Backing strap fixed by tack welding.		>
-----	---	--	---

and a different connection type 351

nr.	description of the main types	symbol
351	Double bevel weld of ordinary quality, perpendicular to the direction of force, between crossing parts.	





## Very great notch behavior group K4

nr.	description of the main types	symbol
412	Parts of different thickness, jointed by a butt weld of ordinary quality, perpendicular to the direction of force. Asymmetrical joint without slope.	

and a different connection type 451

451	Fillet welds of normal quality or single bevel weld (included fillet weld) with backing, perpendicular to the direction of force, between crossing parts.		
-----	---	--	--

# Fatigue resistance depends on stress direction


Stress perpendicular to weld	Stress parallel with weld	Shear
K1  ↗ P or P100 ↖ P or P100	K0  ↙ P or P100 ↖ P or P100	K0 
K2  ↗ P or P100	K1  ↖ P or P100	
<b>No weld (all directions)</b>		
W0 	In the software: $\tau_D(-1) = \sigma_D(-1) / \sqrt{3}$	

Steel Grade	$\sigma_D(-1)$ for $\kappa=-1$ elemt group 5 St 52-3							
Notch group	W0	W1	W2	K0	K1	K2	K3	K4
Stress amplitude	163.8	130.3	104.2	118.8	106.1	89.1	63.6	38.2


# 1. For beams SCF of connections can be included in the classification

Depends on Stress concentrations:


## Slight notch behavior group K0

013	Gusset, jointed by cutt welds of special quality, perpendicular to the direction of force.		 
-----	--	---	--


## Moderate notch behavior group K1

113	Gusset, jointed by butt welds of ordinary quality, perpendicular to the direction of force.		 
-----	---	---	--


## Medium notch behavior group K2

213	Butt weld of special quality and continuous part, both perpendicular to the direction of force, at a crossing of flanges with in-welded corner plates. The ends of the welds are ground to prevent them from notch behaviour.		 
-----	---	---	--

## Great notch behavior group K3

313	Butt weld of ordinary quality and continuous part both perpendicular to the direction of force, at a crossing of flanges with welded corner plates. The ends of the welds have been ground to prevent them from notch behaviour.		 
-----	--	--	---

## Very great notch behavior group K4

413	Butt weld of ordinary quality, perpendicular to the direction of force, at a crossing of flanges without corner plates.		 
-----	---	---	--

(not included in this tutorial)

# Weld Type classification

1

Press *Define* for the Weld Type.

2

Select *Weld Type W0*. Press *Apply* to Full Model condition.

3


Press *Add Condition*. Select All Welds Condition and select operation *Add*. Press *OK*.

4

Select *Weld Type: K1*.

5

Select direction X. Press OK.



# Weld Type classification 2

6

Press Add Condition.

Selection: All Welds.

Weld Type: K2.

Direction: Y.

Press OK.

7

Press Add Condition.

Selection: All Welds




Weld Type: K0.

Direction: XY.

Press OK.

8

Press OK.



# Weld Type classification intersecting welds

9

Press *Add Condition*.


Selection: All Weld intersections.

Weld Type: K2.

Direction: X.

Press OK.

The last line in the classification overwrites the previous lines  
Therefor the settings of all weld intersections overwrites its original setting of K1 in X direction



At intersecting welds all stresses are perpendicular to the weld direction





# Check classification

Edit Classification

ID	1	Title	Weld Type
Alias	WeldType		
Description	<input type="button" value="▼"/>		
Classification			
Weld Type	K0		<input type="button" value="Apply"/>
Element(s) Classification			
No.	Selection	Classification	
1	Full Model	W0	
2	All welds	K1 (X)	
3	All welds	K2 (Y)	
4	All welds	K0 (XY)	
5	All welds intersections	K2 (X)	

 Import Welds





# Element Group classification

1


Press *Define* for the Element Group.

2

Select Element Group: **E6**. Press *Apply*.

3

Press *OK*.



# Material Type classification

1

Press *Define* for the Material Type.

2

Select Material Type: **Fe360 (Fe 37)**.  
Press *Apply*.


3

Press *OK*.

4

Press *OK* to create Standard.

**Material Type** defines which steel is used: St37 or St52. Stress Fatigue values are different for different materials.



# Create extreme table


1

Execute **Extreme Table** in **Fatigue Check** context menu.

2

Load: **1..Load Group1**.

Fatigue check supports only Load Groups. If only one load group exist in the project it will be selected automatically.



3

Table Type: **Parameter over Directions**.

4

Parameter: **Utilization Factor**.

5

Selection: **All Entities**.

6

Press **Fill Table**.

7

Press **OK**.

A screenshot of the 'Extreme Table' dialog box. The dialog has several sections: 'Check' (2. Fatigue Check), 'Load Group' (1..Load Group 1), 'Table Type' (Parameter over Directions), 'Parameter' (Utilization Factor), and 'Selection' (+ All Entities). Below these are fields for 'Elements' (39707) and a 'Fill Table' button. To the right is a preview table showing data for X, Y, Z, XY, YZ, ZX, Eqv., and Overall columns. The 'OK' button at the bottom right is highlighted with a red box. The table data is as follows:

# Create components extreme table

1

Execute *Components Table* in **Fatigue Check** context menu.

2


Select All except 7, 8, 9.

3

Press *Fill Table*.

4

Press *OK*.



The dialog box has a title bar 'Components Extreme Table'. It includes fields for 'ID' (2), 'Title' (empty), 'Description' (empty), 'Check' (2.Fatigue Check), 'Load Group' (1.Load Group 1), 'Table Type' (Parameter Over Directions), and 'Parameter' (Utilization Factor). Below these are 'Selections (9)' and a list of properties. A red box highlights the 'Fill Table' button (3.) and the 'OK' button (4.).

Selections	X	Y	Z	XY	YZ
4..stl plt 10 mm thks	0.69	0.94		0.29	
5..stl plt 8 mm thks	0.41	0.49		0.23	
6..stl plt 15 mm thks	2.12	1.15		1.54	
10..stl plt 4 mm thks	0.40	0.41		0.04	
11..stl plt 12 mm thks	1.39	1.73		1.25	
12..stl plt 24 mm thks					
13..stl L-bar 100x65x8 mm	1.14				
14..stl L-bar 100x65x8 mm (top)	0.77				
15..stl L-bar 100x65x8 mm (side)	1.07				

Components table displays results for multiple selections (e.g. properties, materials or components). For linear properties (beams, bars etc.) only X, Equivalent and Overall directions are displayed. If no elements belong to the property - empty fields are displayed.

# Create criteria plot

1

Execute *Criteria Plot* in **Fatigue Check** context menu

2

Parameter: **Utilization Factor**

3

LG Parameter: **Absolute**

LG Parameter – enabled only for Load Groups. It defines which values to take (minimum, maximum or absolute maximum)

4

Direction: **Overall**

5


Point of interest: **Total**

6

Press  to preview Plot in Femap

7

Press OK



# Report. Tables and plots

1

Execute Reports => Add Report Designer  
=> Results.

2

Click on **Tables** in **Fatigue Check** context menu.

3

Type: **Extreme**.

4


Selection: **All Entities**.

5

Parameter: **Utilization Factor**.

6

Press **OK**.



# Report. Tables and plots

1

Click on *Criteria Check Plot* in Fatigue Check context menu.

2

Parameter: **Utilization Factor**.

3

Direction: **Overall**.

4

Point of Interest: **Total**.

5


Selection: **All Entities**.

6

Press OK.

7

Generate  check item



# Report. Results


## 2..Fatigue Check

Property	Value
Category	Elemental Custom Check
Selection	All Entities
Parameters	4
Alias (Parameter)	Kappa (Kappa Factor) if(SweldAbs > 0, SweldMin / SweldMax, SweldMax / SweldMin)
All	Sf (Stress Fatigue) Min(units.FromPaToCurrent(Switch(MaterialType, Fe360, Sf_Fe360 (ElementGroup, WeldType), Fe510, Sf_Fe510(ElementGroup, WeldType))), Static_Check.Sallow)
Alias (Parameter)	Sallow_fatigue (Allowable Stress Fatigue) if (Kappa > 0, if(SweldAbs > 0, (5 / 3 * Sf) / (1 - (1 - (5 / 3 * Sf) / (0.75 * tensile)) * Kappa), (2 * Sf) / (1 - (1 - (2 * Sf) / (0.9 * tensile)) * Kappa)), if (SweldAbs > 0, (5 * Sf) / (3 - 2 * Kappa), (2 * Sf) / (1 - Kappa))) 0
Eqv.	
Alias (Parameter)	Uf (Utilization Factor) Abs(SweldAbs) / Min(Static_Check.Sallow, Sallow_Fatigue) Abs(SweldAbs) / (Min(Static_Check.Sallow, Sallow_Fatigue) / if(WeldType <= Weld_K4, SQRT(2), SQRT(3))) Abs(SweldAbs) / (Min(Static_Check.Sallow, Sallow_Fatigue) / if(WeldType <= Weld_K4, SQRT(2), SQRT(3))) Abs(SweldAbs) / (Min(Static_Check.Sallow, Sallow_Fatigue) / if(WeldType <= Weld_K4, SQRT(2), SQRT(3))) pow(me.x, 2) + pow(me.y, 2) + pow(me.z, 2) + pow(me.xy, 2) + pow(me.yz, 2) + pow(me zx, 2) - sign(SweldAbs.X) * me.x * sign(SweldAbs.Y) * me.y - sign(SweldAbs.Y) * me.y * sign(SweldAbs.Z) * me.z - sign(SweldAbs.Z) * me.z * sign(SweldAbs.X) * me.x Max(me.x, me.y, me.z, me.xy, me.yz, me.zx, sqrt(me.eqv / 1.1))
Overall	

## Utilization Factor (LG1, All Entities)

Standard	1..FEM 1.001		Check Parameter	2..Fatigue Check Utilization Factor				
Load Group	1..Load Group 1			Selection	All Entities			
Extreme	X	Y	Z	XY	YZ	ZX	Equiv.	Overall
Minimum								
Value	0.00	0.00		0.00			0.00	0.00
Element ID	37146	83465		11761			83624	83621
Maximum								
Value	2.12	1.73		1.54			4.55	2.12
Element ID	1139	37547		30842			1139	1139
Absolute								
Value	2.12	1.73		1.54			4.55	2.12
Element ID	1139	37547		30842			1139	1139

## Absolute Overall Utilization Factor (LG1, All Entities, 1..Default View)



Check	2..Fatigue Check	Point	Total
Load Group	1..Load Group 1	Parameter	Overall Utilization Factor
Selection	All Entities	View	1..Default View

# Fatigue calculation with Eurocode 3

SDC Verifier 4.0.1 - C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001.sdcv

File Settings Model Recognition Job Tools Standard Report Help

F1 Go To Embed Mode

Panel Finder  
Weld Finder  
Stiffened Panels Finder

Jobs (1)  
1. Job 1  
Individual Loads (5)  
Load Sets (4)  
Load Groups (1)  
Fatigue Groups (0)  
Tables (0)  
Plots (0)

Tools  
Standards (1)  
Add  
Remove Multiple  
Clear Checks results  
Load From Library  
3..Material Type  
Standard Tables (2)  
Checks (3)  
1..Static Stress Check  
2..Fatigue Check  
Tables (1)  
Plots (1)  
3..Fatigue Summation

Reports (0)

ANSI/AISC 360-10  
API RP 2A LRFD (1st, Jul 1993)  
DIN 15018  
Eurocode 3  
F.E.M. 1.001  
ISO 19902 (1st, Dec 2007)  
Norsok N004 (rev.3, Feb 2013)  
Plate Buckling ABS 2004  
Plate Buckling ABS 2014  
Plate Buckling DNV CN30/1995  
Plate Buckling DNV RP-C201 2010  
Custom

22:50:31 C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001.sdcv  
22:55:23 Saving backup file...  
22:55:23 C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001\_autobackup.sdcb saved  
23:00:23 Saving backup file...  
23:00:23 C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001\_autobackup.sdcb saved  
23:05:23 Saving backup file...  
23:05:23 C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001\_autobackup.sdcb saved  
23:10:23 Saving backup file...  
23:10:23 C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001\_autobackup.sdcb saved

Nodes: 37803 Elements: 39707 Fem Model: C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001.modfem

# Eurocode 3 settings

Eurocode 3       Edit Classification

ID	2	Title	Eurocode 3
Description			
FAT Class	<input type="text"/>	Define	
Reduced Range	2..Reduced Range	Define	
Consequence of Failure	Low		
Assessment Method	Damage tolerant		
Safety Factor (Gamma_Mf)	1		
Materials with Yield or Tensile = 0	0		Unit System MKS (Meter/Kg/Second)
<input type="button" value="OK"/> <input type="button" value="Cancel"/>			

**Selection**

**All**

+ All Entities

Elements 39707

**Classification**

**Reduced Type**

Magnitude of the compressive portion of the stress range

In non-welded details or stress-relieved welded details the effective stress range may be calculated by adding the tensile portion of the stress range and 60% of the magnitude of the compressive portion of the stress range

**Element(s) Classification**

No.	Selected	Type
1	Full Model	Not Reduced

# Eurocode 3 formula's

Fatigue Check

ID	2	Title	Fatigue Check
Alias	Fatigue		
Description	<input type="button" value="▼"/>		
<input checked="" type="checkbox"/> Show Parameter Description			

Options

Calculate Results over Directions  
 Calculate Results over Points

Load Calculation      Load Group Summation

Selection      All Entities

Parameters (8) / Replacements (0)


**Parameter = Delta\_stress (Delta Stress)**  
Description: The delta stress is the stress difference for a load group. For the equivalent delta stress the standard formula is used with the delta stress as input. The overall results give the maximum delta stress of the group in each of the 7 directions.  
All: if(ReducedRange = NotReduced, SweldDelta, if(SweldMax < 0, 0.6 \* SweldMax, SweldMax) - if(SweldMin < 0, 0.6 \* SweldMin, SweldMin))  
XY: SweldDelta  
YZ: SweldDelta  
ZX: SweldDelta  
Eqv.: sqrt(pow(me.x,2) + pow(me.y,2) + pow(me.z,2) - me.x \* me.y - me.y \* me.z - me.z \* me.x + 3 \* (pow(me.xy, 2) + pow(me.yz, 2) + pow(me.zx, 2)))  
Overall: AbsMax(me.x, me.y, me.z, me.xy, me.yz, me.zx, me.eqv)

**Parameter = m (m)**  
All: if(ItemNumberOfCycles <= 5M, 3, if(ItemNumberOfCycles < 100M, 5, 1))

**Parameter = Fs (Fatigue Strength)**  
Description: Maximum delta stress for the number of load cycles in the group.  
All: if(ItemNumberOfCycles <= 5M, pow(SN(1, FAT), m) \* 2M, if(ItemNumberOfCycles <= 100M, pow

Clear results

# FAT classes (similar to weld/notch groups)



# FAT classes Eurocode 3




Figure 7.1: Fatigue strength curves for direct stress ranges

# FAT classes Eurocode 3

For determination of FAT classes check standard!  
In this tutorial only examples are given


No welds:


Table 8.1: Plain members and mechanically fastened joints


Detail category	Constructional detail	Description	Requirements
160	<p><b>NOTE</b> The fatigue strength curve associated with category 160 is the highest. No detail can reach a better fatigue strength at any number of cycles.</p> 	<p><u>Rolled and extruded products:</u></p> <ul style="list-style-type: none"><li>1) Plates and flats;</li><li>2) Rolled sections;</li><li>3) Seamless hollow sections, either rectangular or circular.</li></ul>	<p><u>Details 1) to 3):</u></p> <p>Sharp edges, surface and rolling flaws to be improved by grinding until removed and smooth transition achieved.</p>

100 $m = 5$		<p>(6) and (7) Rolled and extruded products as in details 1), 2), 3)</p>	<p><u>Details 6) and 7):</u></p> <p><math>\Delta t</math> calculated from: <math>\tau = \frac{V S(t)}{I t}</math></p>
----------------	--	--	---



# FAT classes Eurocode 3 welded

100	 <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">7</span>	<p>7) Repaired automatic or manual fillet or butt welds for categories 1) to 6).</p> <p>7) Improvement by grinding performed by specialist to remove all visible signs and adequate verification can restore the original category.</p>
-----	--	---

80	size effect for $t > 25 \text{ mm}$ : $k_s = (25/t)^{0.2}$		<p>9) Transverse splices in welded plate girders without cope hole.</p> <p>10) Full cross-section butt welds of rolled sections with cope holes.</p> <p>11) Transverse splices in plates, flats, rolled sections or plate girders.</p> <p><math>\leq 0.2b</math></p>	<ul style="list-style-type: none"> <li>- The height of the weld convexity to be not greater than 20% of the weld width, with smooth transition to the plate surface.</li> <li>- Weld not ground flush</li> <li>- Weld run-on and run-off pieces to be used and subsequently removed, plate edges to be ground flush in direction of stress.</li> <li>- Welded from both sides; checked by NDT.</li> </ul> <p><u>Detail 10:</u> The height of the weld convexity to be not greater than 10% of the weld width, with smooth transition to the plate surface.</p>
----	---	---	--	--

80	$m=5$		<p>8) Continuous fillet welds transmitting a shear flow, such as web to flange welds in plate girders.</p> <p>9) Fillet welded lap joint.</p>	<p>8) <math>\Delta t</math> to be calculated from the weld throat area.</p> <p>9) <math>\Delta t</math> to be calculated from the weld throat area considering the total length of the weld. Weld terminations more than 10 mm from the plate edge, see also 4) and 5) above.</p>
----	-------	---	---	---

# Eurocode 3 Fatigue resistance

Stress perpendicular to weld	Stress parallel with weld	Shear
80 	100 	80 
No weld (normal direction)		No weld (shear)
160 	100 	


# Set FAT classes

Edit Classification

ID	1	Title	FAT Class
Alias	FAT		
Description			
Classification			
FAT Stress	160	Apply	
Element(s) Classification			
No.	Selection	Classification	
1	Full Model	160	
4	All Entities	100 (XY, YZ, ZX)	
2	All welds	100 (X)	
3	All welds	80 (Y, XY)	
5	All welds intersections	80 (X)	


Plot

Parameters  
Direction X



Plot

Parameters  
Direction Y



15.  
14.  
13.  
12.  
11.  
10.  
9.  
8.  
7.  
6.  
5.  
4.  
3.  
2.  
1.

15.  
14.  
13.  
12.  
11.  
10.  
9.  
8.  
7.  
6.  
5.  
4.  
3.  
2.  
1.

# Set fatigue groups and number of cycles

The screenshot shows the SDC Verifier 4.0.1 software interface. The left sidebar displays a tree view of project components: Jobs (1), Tools (2), and Standards (2). Under Jobs, 'Job 1' is expanded, showing Individual Loads (5), Load Sets (4), Load Groups (1), and Fatigue Groups (0). Under Tools, 'Checks (3)' is selected, showing 1..Static Stress Check, 2..Fatigue Check, and 3..Fatigue Summation. Under Standards, '1..FEM 1.001' is selected, showing FEM Constants, Characteristics, Classifications (Weld Type, Element Group, Material Type), Standard Tables, and Checks.

The main workspace is titled 'Add Fatigue Group'. It contains fields for 'ID' (set to 1), 'Title' (empty), 'Description' (empty), and 'Fatigue Item Cycles' (set to 1). Below these are two tables: 'LG1 | 1..Load Group 1' and '1..Load Group 1'. The second table has a value '2e6' in its 'Fatigue Item Cycles' column, which is circled in red. A callout box points to this value with the text: 'Set number of cycles for this group with stress variation'. At the bottom of the workspace, there is a 'Total amount of cycles' field set to '2000000' and a 'Create' button, which is also circled in red.

The bottom of the screen shows a command history window with the following log entries:

```
23:40:23 Saving backup file...
23:40:23 C:\Users\bos\OneDrive\sdVerifier\examples\F.E.M. 1.001_autobackup.sdcb saved
23:42:24 Selection is empty
23:45:23 Saving backup file...
23:45:23 C:\Users\bos\OneDrive\sdVerifier\examples\F.E.M. 1.001_autobackup.sdcb saved
23:49:49 Fatigue Group '1..Fatigue Group 1' created
23:50:23 Fatigue Group '1..Fatigue Group 1' removed
23:50:23 Saving backup file...
23:50:23 C:\Users\bos\OneDrive\sdVerifier\examples\F.E.M. 1.001_autobackup.sdcb saved
```

At the bottom, the status bar displays: Nodes: 37803 Elements: 39707 Fem Model: C:\Users\bos\OneDrive\sdVerifier\examples\F.E.M. 1.001.modfem

# Calculate and show fatigue damage

The screenshot shows the SDC Verifier 4.0.1 software interface. The main window title is "SDC Verifier 4.0.1 - C:\Users\bos\OneDrive\sdcverifier\examples\F.E.M. 1.001.sdcv". The menu bar includes File, Settings, Model, Recognition, Job, Tools, Standard, Report, and Help. The toolbar contains various icons for file operations and analysis.


The left sidebar navigation tree includes:

- Recognition
  - Joints
    - Beam Member Finder (3)
    - Panel Finder
    - Weld Finder
    - Stiffened Panels Finder
  - Jobs (1)
    - 1..Job 1
      - Individual Loads (5)
      - Load Sets (4)
      - Load Groups (1)
        - 1..Load Group 1
      - Fatigue Groups (1)
        - 1..Fatigue Group 1
  - Tools
    - Standards (2)
      - 1..FEM 1.001
      - 2..Eurocode 3
        - Constants (9)
        - Characteristics
        - Classifications (2)
        - Standard Tables (1)
    - Checks (2)
      - 1..Yield Check
      - 2..Fatigue Check
  - Reports (0)

# Better subdivision of load cycles

- ▶ A better fatigue damage can be made if load cycles are specified more accurately.
- ▶ Instead of 2 million load cycles from start to end:


Load cycle	Number of cycles	Content
L4-L1	0,5 e6	LS4, LS3, LS2, LS1, IL1
L4-L2	1,0 e6	LS4, LS3, LS2, IL1
L4-L3	0,5 e6	LS4, LS3, IL1



**NB gravity load is also included because the stress variation determines the fatigue damage**

# Make new load cycle groups

## Create load group L4-L3



- Create load group L4-L2 in the same way
- Rename Load Group I into L4-L1

# Create fatigue groups and set # of cycles

The screenshot shows the SDC Verifier software interface. On the left, the project tree displays a 'Jobs (1)' section with '1..Job 1' containing 'Individual Loads (5)' and 'Load Groups (3)'. A red circle highlights the 'Fatigue Groups (1)' item under '1..Job 1'. In the center, the 'Add Fatigue Group' dialog is open. The 'Title' field is set to 'Detailed load cycles pattern'. The 'Fatigue Item Cycles' field contains '1'. A table lists three items: '1..L4-L1' (cycles: 5e6), '2..L4-L3' (cycles: 1e6), and '3..L4-L2' (cycles: 5e6). A red arrow points from the 'Set number of cycles' callout to the '1' in the 'Fatigue Item Cycles' field. Another red arrow points from the 'Create' button to the 'Total amount of cycles' field, which contains '2000000'. A red box encloses the 'Total amount of cycles' field and the 'Create' button. A red callout box at the bottom right states: 'Total number of load cycles is calculated automatically'.

SDC Verifier 4.0.1 - C:\Users\bos\OneDrive\projects\allseas\_course\F.E.M. 1.001\F.E.M. 1.001\_2.sdcv

File Settings Model Recognition Job Tools Standard Report Help

TANK

Settings

- Unit System
- Legend Settings
- Number Formats
- Views (1)

Model

Recognition

Jobs (1)

- 1..Job 1
  - Individual Loads (5)
    - 1..Gravity.Mounting surface
    - 2..L1.Mounting surface
    - 3..L2.Mounting surface
    - 4..L3.Mounting surface
    - 5..L4.Mounting surface
  - Load Sets (4)
  - Load Groups (3)
    - 1..L4-L1
    - 2..L4-L3
    - 3..L4-L2
- Fatigue Groups (1)
  - 1..Overall damage

Tables (0)

Plots (0)

Tools

Standards (1)

- 1..Eurocode 3
- Constants (9)

Add Fatigue Group

ID: 2 Title: Detailed load cycles pattern

Description:

Fatigue Item Cycles: 1 Set

1..L4-L1	.5e6
2..L4-L3	1e6
3..L4-L2	.5e6

Total amount of cycles: 2000000 Create

Total number of load cycles is calculated automatically

# Calculate and show fatigue damage

The screenshot shows the SDC Verifier 4.0.1 software interface. On the left, the navigation tree includes sections like Recognition, Jobs, Tools, Standards, and Reports. In the 'Tools' section, 'Fatigue Check' is selected, highlighted with a red box. A context menu for 'Fatigue Check' is open, with 'Contour Plot' also highlighted with a red box. The main workspace displays a dialog box for 'Check Fatigue Contour Plot'. The 'Check' field is set to '2..Fatigue Check'. Under 'Options', 'Parameter' is set to 'Summed Damage' and 'LG Parameter' to 'Absolute'. In the 'Selection' panel, 'All Entities' is selected. The 'Data Conversion' section contains a checked checkbox labeled 'No Averaging', which is also highlighted with a red box. A red arrow points from this checkbox to a callout box in the bottom right corner containing the text: 'No average because results from welds are different from non weld results'. The status bar at the bottom shows log messages and counts: 'Nodes: 37803 Elements: 39707'.